

### **Schematic Verification Tasks**

Check	Team Member	Sign Off
Checked Accuracy of Connections	Brandon	B.B.
Schematic Checked for Part Values	Julia G	J.G.
Bypass Capacitors for Each Active Component	Julia R	J.R.
Correct Footprints in Schematic Database	AJ	A.C.

### **PCB Verification Tasks**

Check	Team Member	Signed Off Date
PCB Footprints Checked	Brandon	B.B.
PCB Parts Orientation and Placement Approved	AJ	A.C.
PCB Design Rules Verified	Julia R	J.R.
Team Name/Student Name on TOP SILKSCREEN	Julia G	J.G.
PCB Verification run Connectivity Check	Rex	R.S.
CAM Submission to FREEDFM	Rex	R.S.
Errors from FREEDFM Corrected	Rex	R.S.

### **Team Member Sign Offs**

Team Member 1: Rex Serpe, 10/8/21

Team Member 2: Julia Rudy, 10/8/21

Team Member 3: Julia Graham, 10/8/21

Team Member 4: Brandon Brnich, 10/8/21

Team Member 5: AJ Cuddeback, 10/8/21